

M3-ATX Serial cable with certain mainboards

With some mainboard's serial header pinout you get a Timeout error while trying to program M3-ATX.
To fix it, you need to modify the serial cable harness :

